

Attorney Docket No. 5649-966DV



PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re: Jeung

Application Serial No.: 10/718,344

Filed: November 20, 2003

For: *Methods of Reading and/or Writing Data to Memory Devices Including Multiple Write Circuits and/or Virtual Ground Lines and Related Devices*

U.S. Patent No.: 6,798,700 *B2*

Issued: September 28, 2004

Date: November 23, 2004

Commissioner for Patents
Attn: Certificate of Correction Branch
P.O. Box 1450
Alexandria, VA 22313-1450

Certificate
DEC 01 2004
of Correction


**REQUEST FOR ENTRY OF CERTIFICATE OF CORRECTION UNDER
35 U.S.C §254 AND 37 C.F.R. §1.322**

Sir:

The Assignee of record for the above-referenced patent hereby requests, pursuant to 35 U.S.C §254 and 37 C.F.R. §1.322, that a Certificate of Correction be issued. This request is made in order to correct the mistakes incurred through the fault of the U.S. Patent and Trademark Office. No fee is believed due. However, the Commissioner is authorized to charge any deficiency or credit any overpayment to Deposit Account No. 50-0220.

The mistakes appearing in the patent are set forth with corrections on the Certificate of Correction enclosed herewith, with an additional copy thereof and a return post card.


Respectfully submitted,


Scott C. Hatfield
Registration No. 38,176

Myers Bigel Sibley & Sajovec, P.A.
P. O. Box 37428
Raleigh, North Carolina 27627
Telephone: (919) 854-1400
Facsimile: (919) 854-1401
Customer No. 20792

Certificate of Mailing under 37 CFR 1.8

I hereby certify that this correspondence is being deposited with the United States Postal Service with sufficient postage as first class mail in an envelope addressed to: Commissioner for Patents, Attn: Certificate of Correction Branch, P.O. Box 1450, Alexandria, VA 22313-1450 on November 23, 2004.


Monica L. Croom

DEC 03 2004

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,798,700 *B2*
DATED : September 28, 2004
INVENTOR(S) : Jeung

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In the Claims:

Column 10, line 39 should read -- generating a control signal on a control line coupled to a --

Column 14, line 28 should read -- ground line is set to a first of the ground voltage or the --

Column 14, line 31 should read -- wherein the virtual ground line is set to a second of the --

MAILING ADDRESS OF SENDER:
Myers, Bigel, Sibley & Sajovec
P.O. Box 37428
Raleigh, NC 27627

PATENT NO. 6,798,700
No. of additional copies: _____



This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you are required to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

DEC 03 2004